Form: mrocess

Monday, 2/5/2007 8:08:37 AM Date: Kim Johnston User: **Process Sheet** : LANYARD ASSEMBLY **Drawing Name** Customer : CU-DAR001 Dart Helicopters Services Job Number : 30611 **Estimate Number** : 10942 : D26905 : N )A Part Number P.O. Number S.O. No. : 1 1A D2690 REV. B2 **Drawing Number** This Issue : 2/5/2007 : N/A Project Number Prsht Rev. MA : B2 Type : SMALL /MED FAB **Drawing Revision** First Issue : NA : 25945 Material Previous Run : 2/12/2007 30 Um: Each Qty: Due Date Written By Checked & Approved By 01/08.24 Removed Manufacturer Release : Est: C Comment Certification SM/EC **Additional Product** Job Number: Description: Seq. #: Machine Or Operation: Loop Sleeve 1.0 Comment: Qty.: 2.0000 Each(s)/Unit Total: 60.0000 Each(s) Loop Sleeve Pick: Description Batch Qty Part Number M100644. Loop Sleeve 2 CBL-460 2.0 CBL1240 Comment: Qty.: 0.6250 f(s)/Unit Total: 18.7500 f(s) Cable Pick: Part Number Description Qty Cable 7.5" CBL-1240 SMALL & MEDIUM FAB RESOURCE 1 SMALL FAB 1 3:0 Comment: SMALL & MEDIUM FAB RESOURCE 1 Assemble as per Dwg D2690 INSPECT WORK TO CURRENT STEP 4.0 QC5 20 30 Comment: INSPECT WORK TO CURRENT STEP PACKAGING RESOURCE #1 PACKAGING 5.0 Comment: PACKAGING RESOURCE #1 Identify and Stock Location:

Page 1

<b>Dart</b>	Aeros	pace	Ltd
-------------	-------	------	-----

W/O:		WORK ORDER CHANGES										
DATE	STEP	PR	OCEDURE CHANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC inspector			
								·				
Part No	):	PAR #:	Fault Category:		ICR: Yes	(Nd DO	A: <u></u>	Nate: △	460/22			

QA: N/C Closed: \_\_\_\_ Date: \_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
DATE	STEP Description of No Section A	Description of NC		Corrective Action	Section B		Varification		Τ		
			Initial Chief Eng	Action Descri Chief Eng	otion	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector		

NOTE: Date & initial all entries

Date:

Monday, 2/5/2007 8:08:37 AM

User:

Kim Johnston

**Process Sheet** 

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: LANYARD ASSEMBLY

Job Number: 30611

Part Number: D26905

Job Number:



Seq. #:

Machine Or Operation:

Description:

6.0

QCŽ1

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



U D.5222

## **Dart Aerospace Ltd**

W/O:		WORK ORDER CHANGES											
DATE	STEP	PROCEDURE CHANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector					
Part No	·	PAR #: Fault Category:	NC	R: Yes	No DQA		_ Date: _						


QA: N/C Closed: \_\_\_\_ Date: \_\_\_\_


NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
	STEP	Description of NC		Corrective Action	Section B		Verification	Approval Chief Eng	Approval QC Inspector		
DATE		Section A	Initial Chief Eng	Action Descri Chief Eng	tion	Sign & Date	Section C				
									1		
					•						
					,						
					,						
					¥*						

NOTE: Date & initial all entries



	DESIG	NOW TO	DRAWN BY	DART AEROSPACE LTD VICTORIA INTERNATIONAL AIRPORT, CANADA
	CHECK	KED <sub>A</sub> /	APPROVED	DRAWING NO. REV. B
	$\mathcal{V}$	nw,	BW	D2690 SHEET 1 OF 1
	DATE		L	TITLE SCALE
	97.1	0.02		LANYARD ASSEMBLY NTS
	Α	-	97.07.03	NEW ISSUE
	Ŗ		97.10.02	REVISED NOTE FOR ADDITIONAL LENGTH
	Bı	of cr	01.08.20	ADD NOTE TO REMOVE 2.25" OF SLEEVE
200	BZ	# 19	= 04.06.24	ADDED TOLERANCE





D2690-X

X = LENGTH IN INCHES

CUT CABLE 2.50\* INCHES LONGER THAN 'X' LENGTH. NOTE:

FOLD ENDS TIGHT TO 'X' LENGTH AND CRIMP WITH

SLEEVE AT END OF LOOSE END OF CABLE WITH

CBL-705 CRIMPING TOOL.

\*ADDITIONAL LENGTH MAY BE NECESSARY IN

SOME APPLICATIONS. CUT AS REQUIRED.

RETURN TO ENGINEERING UNCONTROLLED COPY

SHOP COPY

UNCONTROLLING
UN NOTE:

ASSEMBLY WITH ATTACHING PARTS.

DEO's

